FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer — Vishnu R, AE, LSGD
2. Name of the School — Mother theresa Memorial Central School
3. Location with name of Education District/ Sub. District — Pulippara, Pangode P.O
4. Classification of Building as specified in column 4 of the application for fitness certificate and size. — office 11.10 × 8.55 (G.F)
   11.10 × 4.05 (F.F)
   Block I - 28.40 × 8.60 (3 storied)
   Block II - 28.10 × 10.62 (2 storied)
   Block III - 24.30 × 8.20 (2 storied
   6.43 × 6.81 (building)
5. Period for which the certificate is issued — 2021 June to 2022 March
6. Nature of defects , if any
   a) Foundation and basement — Nil
   b) Superstructure
   c) Doors and Windows
   d) Wood work wrought and put up
   e) Roof
   f) Flooring
   g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner — Nil
8. Whether maintenance works have been done properly — Yes
9. Whether the structure is sound or not for conducting classes — Structure is found under

Note : *1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.*

CERTIFICATE

certified that the school building was inspected by me on 17/06/2021 and found to be fit / unfit to conduct classes, for the period 2021 June to 2022 March for the reasons stated above.

Place : Pangode

Date : 18/06/2021

OFFICE OF THE ASSISTANT ENGINEER * LSG SECTION * Pangode Grama Panchayat Date... (Seal)

VISHNU. R. Assistant Engineer LSG Section, Pangode

Assistant Engineer

500/8-6-13